

78°46'45"E 78°47'E arali Village 07.08.2025 (09:30 am) ~450 meter ~750 meter Roads **Deposition of** affected sediments after by floods the flood event Dharali Village 78°47'E 78°46'45"E

Pre-Post Satellite Images depicting damage to the roads- Dharali Village, Uttarkashi District, Uttarakhand, India.

Location Diagram





Interpretation


Satellite image acquired on 7th August, 2025 after the flood event. The impact is seen in Dharali village and surroundings depicting the flood affected buildings, roads, and plantations. The roads affected by floods in the debris deposited area is highlighted.

Data Source

Pre Event Image: Cartosat-3, 13th June 2024 Post Event: Cartosat, 07th August 2025

Frame Work

The best effort rapid mapping product is elaborated within a very short time frame, optimizing the available material, and has been quality checked as per NRSC/ISRO procedures. All geographic information has limitations due to scale, resolution, date and interpretation of the original source material. No liability concerning the content or the use thereof is assured by the producer. Note: When publishing this map as part of any report, source may be indicated as 'NRSC (2025) - Flood Affected areas in Part of Uttarakhand State (as on 07.08.2025)', Map no: 2025/FL/UK/6/07082025, NRSC/ISRO, Hyderabad.





Legend

Roads Affected by Flood

Disaster Management Support Group National Remote Sensing Centre, ISRO Dept. of Space, Govt. of India Hyderabad- 500 037 E-Mail: flood@nrsc.gov.in www.nrsc.gov.in



