78°45′15″E 78°45′30″E




78°45'15"E 78°45'30"E 78°45'30"E



Pre-Post Satellite Images showing damaged buildings -Harsil Village, Uttarkashi District, Uttarakhand, India.

Location Diagram





Interpretation

Satellite image acquired on 7th August, 2025 after the flood event. The impact is seen in Harsil village and surroundings depicting the disappearance of buildings, roads, plantations. Buildings Affected by flood are highlighted.

Data Source

Pre Event Image : Cartosat-3, 13th June 2024 Post Event : Cartosat, 07th August 2025

Legend



Affected Buildings (Post Flood, as on 7th Aug 2025)



Buildings (as on 13th June 2024)

Frame Work

The best effort rapid mapping product is elaborated within a very short time frame, optimizing the available material, and has been quality checked as per NRSC/ISRO procedures. All geographic information has limitations due to scale, resolution, date and interpretation of the original source material. No liability concerning the content or the use thereof is assured by the producer. Note: When publishing this map as part of any report, source may be indicated as 'NRSC (2025) - Flood Inundated areas in Part of Uttarakhand State (as on 07.08.2025)', Map no: 2025/FL/UK/4/07082025, NRSC/ISRO, Hyderabad.





Disaster Management Support Group National Remote Sensing Centre, ISRO Dept. of Space, Govt. of India Hyderabad- 500 037 E-Mail: flood@nrsc.gov.in www.nrsc.gov.in





78°45'15"E