




## Pre-Post Satellite Images - Dharali Village, Uttarkashi District, Uttarakhand, India.

### Location Diagram



### Interpretation


Satellite image acquired on 7th August, 2025 after the flood event. The impact is seen in Dharali village and surroundings depicting the buildings, roads and plantations affected by flood.

### Data Source

Pre Event Image : Cartosat-3, 13th June 2024  
Post Event : Cartosat, 07th August 2025

### Frame Work

The best effort rapid mapping product is elaborated within a very short time frame, optimizing the available material, and has been quality checked as per NRSC/ISRO procedures. All geographic information has limitations due to scale, resolution, date and interpretation of the original source material. No liability concerning the content or the use thereof is assured by the producer.  
Note: When publishing this map as part of any report, source may be indicated as ' NRSC (2025) - Flood Affected areas in Part of Uttarakhand State (as on 07.08.2025)' , Map no : 2025/FL/UK/1/07082025, NRSC/ISRO, Hyderabad.



Disaster Management Support Group  
National Remote Sensing Centre, ISRO  
Dept. of Space, Govt. of India  
Hyderabad- 500 037  
E-Mail: [flood@nrsc.gov.in](mailto:flood@nrsc.gov.in)  
[www.nrsc.gov.in](http://www.nrsc.gov.in)

