


Pre-Post Satellite Images - Harsil Village, Uttarkashi District, Uttarakhand, India.

Location Diagram



Interpretation

Satellite image acquired on 7th August, 2025 after the flood event. The impact is seen in Harsil village and surroundings depicting the damage to buildings, roads, and plantations. The roads affected by floods are highlighted.


Data Source

Pre Event Image : Cartosat-3, 13th June 2024
Post Event : Cartosat, 07th August 2025

Frame Work

The best effort rapid mapping product is elaborated within a very short time frame, optimizing the available material, and has been quality checked as per NRSC/ISRO procedures. All geographic information has limitations due to scale, resolution, date and interpretation of the original source material. No liability concerning the content or the use thereof is assured by the producer. Note: When publishing this map as part of any report, source may be indicated as ' NRSC (2025) - Flood Affected areas in Part of Uttarakhand State (as on 07.08.2025)' , Map no : 2025/FL/UK/5/07082025, NRSC/ISRO, Hyderabad.

0 75 150 300 Meters



Legend

..... Roads Affected by Flood

Disaster Management Support Group
National Remote Sensing Centre, ISRO
Dept. of Space, Govt. of India
Hyderabad- 500 037
E-Mail: flood@nrsdc.gov.in
www.nrsdc.gov.in

